

GOVERNMENT CORNER RESTORATION FORM

Date: 12-17-96 By: JP

Township 27S Range 3W Sec. 27

County DOUGLAS This survey consists of:

State OR Date 12-9-96 No. \_\_\_\_\_

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Designation

1/4 S 28 | S 27

DOUGLAS COUNTY  
Condition Report Only  
SURVEYOR

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1958 RESURVEY

Monument(s) Found: (Condition and Source)

3/4" DIA BRASS CAPONA 2 1/2" O.D.  
IRON PIPE PROTRUDING 2" ABOVE  
GROUND (1958 BLM)

U.S. CADASTRAL SURVEY

T27S R3W

1/4

S28/S27

1958

BUREAU OF LAND MANAGEMENT

Accessories Found:

40" NOW 40" DIA, DOWN CEDAR WITH A FULLY  
HEALED SINGLE BLAZE, ROOTHOLE AGREE'S  
WITH REC. " S 31° E, 51.5 FT (1958)

18" NOW 22" DIA. 2 FT HIGH D/FIR STUMP WITH  
A FULLY HEALED SINGLE BLAZE, BEARS N 1/6° W, 29.0 FT  
(1958)

