

FILED

Date: 9-9-1998 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/20-39

OREGON CORNER RESTORATION FORM

Section 16 Township 24S Range 4W

County DOUGLAS Date 8-12-98

DOUGLAS COUNTY
SURVEYOR

Corner Designation

C 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

5/8" I.R.

BTS: 7" B. OAK N33E 30° GOOD-HEALED - FLAT M91-2 CALLED THIS

BT 6" MAPLE N33E 32° - WE CHOPPED OUT THE FACE -

9" MAPLE N87E 28° GOOD-HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

BTS:

8" MAPLE S2E 26° "C 1/4 BT"

8" CEDAR N46W 14° "C 1/4 BT"

Location & Comments

Compass Declination 19°

Firm/Agency ROSEBURG

FOREST PRODUCTS

Address PO Box 1088

ROSEBURG OR. 97470

Party Chief BILL OLSON

Notes _____

Witness RALPH M. MANUS

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley

OREGON
JULY 28, 1988
MARK F. SMALLEY
2354

RENEWS 6/30/00

C.S. File No. 65/20-39