

FILED

Date: 9-9-98 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/20-40

OREGON CORNER RESTORATION FORM

Section 16 Township 24S Range 4W

County Douglas Date 8-11-98

DOUGLAS COUNTY
SURVEYOR

Corner Designation

N 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. M91-2

Monument(s) & Accessories Found: (Condition and Source)

1963 DCSO IPBC

11" CEDAR S37W 17³ GOOD-HEALED FACE

20" CEDAR N45E 29³ GOOD-HEALED FACE

28" MAPLE N19W 9² ROTTED CENTER- HOLLOW

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

BTS:

9" FIR N62E 12³ "1/4 SBT"

14" ALDER S29E 27³ "1/4 SBT"

Location & Comments

MONUMENT AT FENCE

CORNER FENCES RUN

NORTH, EAST, & WEST

Compass Declination 19°

Firm/Agency ROSEBURG

FOREST PRODUCTS

Address PO Box 1088

ROSEBURG OR. 97470

Party Chief RILL OLSON

Notes _____

Witness RALPH McMANIS

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley

OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

RENEWS 6/30/00

C.S. File No. 65/20-40