

FILED

Date: 9-24-1998 By: SC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/20-41

OREGON CORNER RESTORATION FORM

Section 26 Township 22S Range 8W

County DOUGLAS Date 6-30-98

DOUGLAS COUNTY
SURVEYOR

Corner Designation

N.W/ COR SEC 26
500300

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

- 1963 BLM CAD IPBC
- 11" D. FIR 83° 57' 4" W - GOOD, HEALED FACE
- 8" D. FIR 135° N 48' W - DEAD, HEALED FACE
- 13" D. FIR 21° N 60' E - GOOD, HEALED FACE
- 10" D. FIR 17° S 78' E - GOOD, HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

NONE


New Accessories

16" FIR N20W 143° SCRIEDED "S 22 BT"

Location & Comments

Compass Declination 19 1/2°
 Firm/Agency ROSEBURG FOREST PRODUCTS
 Address PO. Box 1088 ROSEBURG OREGON 97470
 Party Chief Bill Olson
 Notes _____
 Witness RALPH McMANIS

Surveyor's Seal



RENEWS 6/30/00

C.S. File No. 65/20-41

500300-072 ✓