

FILED

Date: 9-24-1998 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/20-42

OREGON CORNER RESTORATION FORM

Section 26 Township 22S Range 8W

County DOUGLAS Date 6-30-98

Corner Designation

W 1/4 COR
500240

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

1963 CAD BLM IPBC

26" W. FIR SBEE 13² - GOOD, HEALED FACE (RECORD - 12.96')

27" W. FIR S27⁴²W 32³⁰ - GOOD HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

NONE

New Accessories

20" FIR N40W 25² SCRIBED "1/4 SBT"

14" W. FIR N78W 27^B SCRIBED "1/4 SBT"

Location & Comments

Compass Declination 19 1/2°

Firm/Agency ROSEBURG

FOREST PRODUCTS

Address P.O. Box 1088

ROSEBURG OR. 97470

Party Chief BILL OLSON

Notes _____

Witness RALPH McMANUS

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley

OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

RENEWS 6/30/00

C.S. File No. 65/20-42