

FILED

Date: 12-31-98 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/20-46

OREGON CORNER RESTORATION FORM

Section 18 Township 23 S. Range 7 W.

County DOUGLAS Date 11/98

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 for Sections 17 and 18

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. ID# 200440

Monument(s) & Accessories Found: (Condition and Source)

FOUND - 1965 BLM BCIP

- 36" FIR, N82 1/2 E, 26<sup>3</sup> Ft, Healed face

- 18" FIR, S75 3/4 W, 12<sup>2</sup> Ft, Healed face

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

- 13" W. FIR, N20W, 22<sup>1</sup>, scribed "1/4 S BT"

- 18" D. FIR, N42E, 40<sup>2</sup>, scribed "1/4 S BT"

Location & Comments

Surveyor's Seal

Compass Declination 19°

Firm/Agency ROSEBURG RESOURCES

Address P.O. BOX 1088

ROSEBURG, OR 97470

Party Chief F. White

Notes F. Raddatz

Witness \_\_\_\_\_

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Mark F. Smalley*

OREGON  
JULY 26, 1988  
MARK F. SMALLEY  
2354

RENEWS 6/30/00

C.S. File No. 65/20-46