

FILED

Date: 1-15-1999 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/23-5

OREGON CORNER RESTORATION FORM

Section 18 Township 23S Range 7W

County DOUGLAS Date " / 98

Corner Designation

1/4 Cor For 18 and 19

DOUGLAS COUNTY
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

Previous Renewals/Surveys, etc. I.D.# 140400

Monument(s) & Accessories Found: (Condition and Source)

FOUND - 1979 BLM BCIP

- FIR 12", N57 1/2 E, 24 1/2 Ft

- FIR 12", S19 1/2 E, 17 1/2 Ft

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

D. fir 9", S47E, 24"

D. fir 13", S66W, 37"

Location & Comments

Surveyor's Seal

Compass Declination 19°

Firm/Agency ROSEBURG RESOURCES

Address P.O. Box 1088

ROSEBURG, OR 97470

Party Chief F. White

Notes F. Raddatz

Witness _____

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley
OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

RENEWS 6/30/00

C.S. File No. 65/23-5

140400-080