

FILED

Date: 11-30-1999 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/23-21

OREGON CORNER RESTORATION FORM

Section 12 Township 26S Range 07W

County Douglas Date 10/25/99

DOUGLAS COUNTY
SURVEYOR

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

East 1/4 Corner Section 12 BC, marked per DCSO record
in good condition
12" D. Fir BT now 24" D. Fir Brq. S16°30'E 43.8' visible
scar and tagged w/ BT tag
9" D. Fir BT now 18" D. Fir Brq. N83°W, 11.8' visible
scar and tagged w/ BT tag

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 19.5°
 Firm/Agency Sweeden
Land Surveying
 Address 5211 Cole Rd
Oakland OR 97462
 Party Chief C. Sweeden
 Notes C. Sweeden
 Witness E. Wilds



Exp. 6/30/00

C.S. File No. 65/23-21