

FILED

Date: 2-17-2000 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/30-2

OREGON CORNER RESTORATION FORM

Section 22 Township 29S Range 8W

County DOUGLAS Date 1-31-00

DOUGLAS COUNTY SURVEYOR

Corner Designation

N 1/4

440400

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)


1958 D.C.S.O. I.P.B.C. SOLID IN GROUND

16" B. OAK N30E 46° GOOD CONDITION - REVERSE SCRIBE ON ATTACHED SLAB

9" FIR N2E 22° FAIR CONDITION - HEALED FACE

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

8" T. CEDAR N35W 33° SCRIBED "1/4 S BT"

9" W. FIR N4E 35° SCRIBED "1/4 S BT"

Location & Comments

Surveyor's Seal

Compass Declination 19 1/2°

Firm/Agency ROSERURG

FOREST PRODUCTS

Address P.O. Box 1088

ROSERURG OR. 97470

Party Chief BILL OLSON

Notes _____

Witness RALPH McMAHIS

REGISTERED PROFESSIONAL LAND SURVEYOR

Mark F. Smalley
OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

RENEWS 6-30-00

C.S. File No. 65/30-2