RESTORED CORNER FOR
STATE OF OREGON – DEPARTMENT OF FORESTRY

Northwest one-sixteenth corner for Section 8, Township 32 South, Range 6 West, W.M., Douglas County, Oregon.

ESTABLISHED by A. G. Gibson, 1974

11/2" x 36" galvanized iron pipe with 3" bronze cap in mound of rock (lying on mound of rock out of place) from which a:

44" Fir S23°W 31.1 ft.; now 48" x 60' high snag in place, face closed.
31" Fir S85°W 53.3 ft.; now 33" x 70" high snag in place, all scribes visible.
4" x 4" x 72" white painted cedar post N83°E 5.3 ft.; missing.

RESTORED:

Cut 12" off of 1974 galvanized iron pipe with 3" bronze cap and reset 18" in concrete in mound of rock from which a:

10" Fir N12°W 20.5 ft. to aluminum nail in BT face scribed NW1/16S8BT.
7" Fir S66°E 10.0 ft. to aluminum nail in BT face scribed NW1/16S8BT.

Bearing tree tags on 10" Fir BT N12°W 20.5 ft. and 7" Fir BT S66°E 10.0 ft.

Magnetic variation set at 20° east.

Dated June 9, 2000

Restored by Tim VanVleet under my direction.
Tim VanVleet

FILED
Date: 7-10-2000 By: JC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 65/30-15

DOUGLAS COUNTY
SURVEYOR

Present and witnessed by Ralph C. Hall

REGISTERED
PROFESSIONAL
LAND SURVEYOR
James M. McIntosh
OREGON
JULY 18, 1984
JAMES M. McINTOSH
2103
Ccrt exp 12-31-2000

C.S. File No. 65/30-15