

**REWITNESSED CORNER FOR  
STATE OF OREGON – DEPARTMENT OF FORESTRY**

Section corner common to Sections 11 and 15, Township 23 South, Range 10 West,  
W.M., Douglas county, Oregon.

**ORIGINAL by Levi Walker, 1906**

4" x 4" x 3' Fir post (missing) from which a:

24" Fir S09°E 85 lks.; now 39" x 3' high rotted stump in place, no marks visible.

24" Fir S57°W 63 lks.; now 52" x 3' high rotted stump in place, scribe T visible on exposed face.

**RESTORATION by Arnold G. Gibson, 1972**

Oregon State Board of Forestry 1 1/2" x 36" galvanized iron pipe with 3" bronze cap (in place) from which a:

13" Fir S26 1/2°W 76.2 ft.; missing.

56" Fir S84°E 40.1 ft.; now 48" x 4' high stump in place, face rotted, axe work visible on bark.

4" x 4" x 72" white painted cedar post S64°E 2.6 ft.; now rotted and fallen over.

**REWITNESSED by Arnold G. Gibson 1976, from the above pipe and cap:**

57" Fir Stump S87°W 15.8 ft.; now 54" x 3' high rotted stump in place, scribes visible on rotting face.

63" Fir stump (original) S09°E 55.0 ft. to face; see above.

**REWITNESSED from above pipe and cap:**

11" Fir S59°E 25.5' to aluminum nail in BT face scribed T23SR10WS11BT.  
Carsonite witness post S43°E 3.65' to base.

8" Fir S26°W 3.4 ft. to aluminum nail in BT face scribed T23SR10WS15BT.  
Carsonite witness post S70°W 2.6 ft. to base.

Bearing tree tag on 11" Fir BT S59°E 25.5 ft. and 8" Fir BT S26°W 3.4 ft.

Magnetic variation set at 20° east.

Dated October 7, 2000

Rewitnessed by Tim VanVleet under my direction.

**FILED**

Date: 10/30/2000 By: sc

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner #/pt. 65/33-3

**DOUGLAS COUNTY  
SURVEYOR**



Expiration date of certificate 12-31-00

Present and witnessed by Ralph C. Hall

C.S. File No. 65/33-3