

FILED

Date: 11/15/2000 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Mpt: 65/33-12

OREGON CORNER RESTORATION FORM

Section 524/519 / 525/530 Township 235 Range 6E7W

County Douglas Date Nov. 13, 2000

DOUGLAS COUNTY SURVEYOR

Corner Designation

524/519
525/530

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

U.S.B.L.M. 1957

U.S.B.L.M. 1986-1995

Monument(s) & Accessories Found: (Condition and Source)

Found corner as reported in U.S.B.L.M. Survey of 1986-1995.

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Compass Declination 20°E

Firm/Agency Shaner Engineering, Inc.

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Claude McLean

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Bruce Shaner

OREGON OCT. 4, 1957 BRUCE A. SHANER 430

Renews June 30, 2007

C.S. File No. 65/33-12