

FILED

Date: 12/19/2000 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Ept: 65/33-15

OREGON CORNER RESTORATION FORM

Section 18 Township 21 S Range 8 W

County Douglas

Date November 2000

DOUGLAS COUNTY SURVEYOR

Corner Designation

N 1/4 S. 18

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Set BY GLO SURVEY - 1945 - Pg 11425

Monument(s) & Accessories Found: (Condition and Source)

Found 1945 BCIP

70" FIR, N74E, 42 IKs - ROTTEN STUMP.

70" FIR, S3 1/2 E, 36 IKs - ROTTEN STUMP

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

16" FIR, S13W, 11⁶ Ft - scribed "1/4 SBT"

7" FIR, S60W, 7⁹ Ft - scribed "1/4 SBT"

10" FIR, N61W, 10⁷ Ft - scribed "1/4 SBT"

12" FIR, N36E, 29⁸ Ft - scribed "1/4 SBT"

Location & Comments

Surveyor's Seal

Compass Declination 19 1/2 °E

Firm/Agency ROSEBURG RESOURCES CO


Address P.O. Box 1088

ROSEBURG, OR 97470

Party Chief Bill Olson

Notes RALPH McMAHIS

Witness _____



RENEWS 6/30/02

C.S. File No. 65/33-15