

Date: 12/19/2000 By: S

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/33-14

OREGON CORNER RESTORATION FORM

Section 12 Township 21 S Range 9 W

County DOUGLAS Date NOVEMBER 2000

DOUGLAS COUNTY
SURVEYOR

Corner Designation

E 1/4 SEC. 12 ONLY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

CS 62/40, CS 63/18, M99-32

Monument(s) & Accessories Found: (Condition and Source)

1967 BLM BCIP

23" FIR, S3W, 72.4', GOOD HEALED FACE

26" FIR, N88 1/2 W, 39.9', GOOD HEALED FACE

11" FIR, N12W, 76.0', FAIR HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

17" FIR, N24E, 16.3', SCRIBED "1/4 S BT"

Location & Comments

Compass Declination 19 1/2 E

Firm/Agency ROSEBURG RESOURCES

Address P.O. Box 1088

Roseburg, OR 97470

Party Chief Bill Olson

Notes Ralph McManis

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley
OREGON
JULY 26, 1988
MARK F. SMALLEY
2364

RENEWS 6/30/02