

FILED

Date: 1-5-2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/33-19

OREGON CORNER RESTORATION FORM

Section 2 Township 25S Range 8W

County Douglas Date Dec 7, 2000

DOUGLAS COUNTY SURVEYOR

Corner Designation

1/4 S
52
S11

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

Corner was set by U.S.B.L.M. in survey of 1979.

Monument(s) & Accessories Found: (Condition and Source)

Found Brass Cap & Bearing Trees as recorded by U.S.B.L.M. in 1979. No change.

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner Engineering, Inc

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes B.A. 52 C. McLean

Witness _____

REGISTERED PROFESSIONAL LAND SURVEYOR

Bruce Shaner

OREGON OCT. 4, 1957 BRUCE A. SHANER 430

C.S. File No. 65/33-19 Renews June 30, 2002