



GARY T. SMITHER

Professional Land Surveyor
Certified Water Rights Examiner

Dec. 2000
Township 21 South, Range 9 West
Section 20

FILED

Date: 1-08-2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/33-24

DOUGLAS COUNTY
SURVEYOR

East ¼ Corner for Section 20: At the ¼ corner found 26" burnt sawed Cedar stump which is the original corner tree and drive a spike in top center. We drive a 6 foot steel post near the corner.

Old Bearing Trees and Reference Monument:

Found BLM brass cap reference monument set in 1966 at N 45° W, 20 links (13.5 feet to our spike in top center) firmly set flush with ground.

34" Cedar at N 79 ½° E, 22 links, now 40" with healed face. Bark is peeling off but tree is still alive. We place new bearing tree tag.

13" Cedar, N 77 ½° W, 30 links is gone.

New Bearing Trees:

12" Fir, S 65° E, 6.7 feet to spike side center scribed "1/4 S21 BT", with new bearing tree tag.

9" Fir, S 27° W, 13.1 feet to spike side center scribed "1/4 S20 BT" with new bearing tree tag.



Gary T. Smither

OREGON
JANUARY 29, 1991
GARY T. SMITHER
2485

expires 6/2002