



GARY T. SMITHER

Professional Land Surveyor
Certified Water Rights Examiner

Dec. 2000

Township 21 South, Range 9 West
Section 20

FILED

Date: 1-8-2001 By: JS

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/33-25

DOUGLAS COUNTY
SURVEYOR

South ¼ Corner for Section 20: Found 1966 BLM Brass Cap on Iron Pipe firmly set flush with ground. We drive a 6 foot steel post near the corner.

Old Bearing Trees:

The 22" rotted Hemlock stump at N 18° E, 38 lks is in complete decay.

5" Alder taken in 1966, now 12" diameter, N 60° E, 30 links, with BLM tag. The old bark scribe is no longer visible. We place new bark scribe "1/4 S20 BT" with a new bearing tree tag.

The 60" fallen Fir at S 10° W, 41 links, is still there.

6" Hemlock taken in 1966, now 22", S 71° W, 63 lks with BLM tag and healed face. We place new bearing tree tag.

New Bearing Trees:

15" Hemlock, N 5° W, 33.8 feet to spike driven in side center, marked "1/4 S20 BT", with bearing tree tag.

14" Hemlock, S 68° E, 16.6 feet to spike driven in side center, marked "1/4 S29 BT", with bearing tree tag.



Expires 6/2002

FAX and Phone (541) 751-9624
P.O. Box 545, North Bend, OR 97459

C.S. File No. 65/33-25