

FILED

Date: 3/20/2001 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/36-18

OREGON CORNER RESTORATION FORM

Section 14 Township 20S Range 7W

County Douglas Date 29 Jan, 2001

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 S13, S14

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Monument(s) & Accessories Found: (Condition and Source)

3 1/4" BLM Brass Cap marked as shown

29" Douglas Fir bears N 06° E <sup>32.3'</sup> 49.7' healed face

35" Douglas Fir bears S 80° W 39.6' healed face

Monument Detail

Sketch

T20S R7W

1/4

S14 | S13

1977

Monument Set (Procedures and Description)

None

New Accessories

18" Douglas Fir bears S 62° W 33.0' blazed, scribed  
"1/4 S14 BT"

18" Douglas Fir bears S 08° E 33.1' blazed, scribed  
"1/4 S13 BT"

Location & Comments

Steel post adjacent  
to corner.

All bearing trees

have red painted

bands and faces

plus yellow bearing

tree tag.

Compass Declination \_\_\_\_\_

Firm/Agency ward

Northwest Inc.

Address P O Box 105

Florence OR 97439

Party Chief Rob Ward

Notes 00-61

Witness Ron Rice

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Robert B. Ward, Jr.  
OREGON  
ROBERT B. WARD, JR.  
JULY 30 1976  
1091

Expires 6/30/02

C.S. File No. 65/36-18