

FILED

Date: 3-20/2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/36-19

OREGON CORNER RESTORATION FORM

Section 14 Township 20S Range 7W

County Douglas Date 29 Jan 2001

DOUGLAS COUNTY
SURVEYOR

Corner Designation

CE 1/16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

3/4" BLM Brass cap marked as shown

9" Douglas Fir bears N 50 1/4° E 83.2' healed face

26" Douglas Fir bears N 12 1/2° W 58.7' healed face

Monument Detail

Sketch

E 1/16

C — C

S14

1989

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Steel post adjacent to corner.

Both bearing trees have red painted bands and faces plus yellow bearing tree tag.

Compass Declination _____

Firm/Agency Ward

North West Inc.

Address P.O. Box 105

Florence OR 97439

Party Chief Ron Rice

Notes 00-61

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert B. Ward, Jr.
OREGON
ROBERT B. WARD, JR.
JULY 30 1976
1091

Expires 6/30/02

C.S. File No. 65/36-19