

FILED

Date: 3/20/2001 By: JC
This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/36-20

OREGON CORNER RESTORATION FORM

Section 14 Township 20S Range 7W

County Douglas Date 29 JAN 2001

DOUGLAS COUNTY
SURVEYOR

Corner Designation

E 1/16 S 14, S 23

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

3 1/4" BLM Brass cap marked as shown

Record 5" Fir S 44° W 16 lks. Found dead and leaning

Record 7" Fir N 16° W 5 1/2 lks. Found dead and down

Monument Detail

Sketch

S 14
E 1/16 —
S 23
1989

Monument Set (Procedures and Description)

None

New Accessories

14" Douglas Fir bears N 30 1/2° W 37.7' blazed, scribed
"E 1/16 U S 14 BT"

18" Douglas Fir bears S 38 3/4° W 39.9' blazed, scribed
"E 1/16 S 23 BT"

Location & Comments

Steel post adjacent
to corner
Both new bearing
trees have red
painted bands and
faces plus yellow
bearing tree tag

Compass Declination _____
Firm/Agency ward
Northwest Inc
Address P O Box 105
Florence OR 97439
Party Chief Rob ward
Notes 00-61
Witness Ron Rice

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert B. Ward, Jr.
OREGON
ROBERT B. WARD, JR.
JULY 30 1976
1091

Expires 6/30/02

C.S. File No. 65/36-20