

FILED

Date: 3-20-2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Ref: 65/36-21

OREGON CORNER RESTORATION FORM

Section 24 Township 20S Range 7W

County Douglas Date 29 Jan 2001

DOUGLAS COUNTY
SURVEYOR

Corner Designation

Section Corner 514 | 513
523 | 524

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

2 1/2" Douglas County Brass Cap marked as shown
60" Douglas Fir bears S40°W 351ks. (record) now down
30" Hemlock bears N18°W 81.5' healed face
16" Douglas Fir bears N62°E 11.2' healed face
16" Hemlock bears N21°W 43.6' healed face
9" Douglas Fir bears S49°E 11.2' healed face

Monument Detail

Sketch

T20S
514 | 513
523 | 524
R7W
1958

Monument Set (Procedures and Description)

None

New Accessories

18" Douglas Fir bears S29°W 5.5' blazed, scribed
T20S R7W S23 BT"

Location & Comments

Steel post adjacent
to corner
All bearing trees
have red painted
bands and faces
plus yellow bearing
tree tag

Compass Declination _____
 Firm/Agency Ward
Northwest Inc
 Address P O Box 105
Florence OR 97439
 Party Chief Rob Ward
 Notes 00-61
 Witness Ron Rice

Surveyor's Seal



Expires 6/30/02

C.S. File No. 65/36-21