

FILED

Date: 3-20-2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Pnt: 65/36-22

OREGON CORNER RESTORATION FORM

Section 24 Township 20S Range 7W

County Douglas Date 29 Jan 2001

DOUGLAS COUNTY
SURVEYOR

Corner Designation

1/4 S13, S24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

2 1/2" Douglas County Brass Cap marked as shown

12" Douglas Fir S 53 1/2° E 26.0' healed face

Monument Detail

T 20 S

S 13

S 24

R 7 W

1958

Sketch

Monument Set (Procedures and Description)

None

New Accessories

14" Hemlock bears N 85 1/2° W 17.2' blazed, scribed "1/4 S13 BT"

18" Douglas Fir bears N 16 1/2° W 38.4' blazed, scribed "1/4 S13 BT"

16" Red Cedar bears S 02 3/4° W 19.1' blazed, scribed "1/4 S24 BT"

Location & Comments

steel post adjacent to corner

All bearing trees have red painted bands and faces plus yellow bearing tree tag

Compass Declination _____

Firm/Agency Ward

Northwest Inc.

Address P O Box 105

Florence OR 97439

Party Chief Rob Ward

Notes 00-61

Witness Ron Rice

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert B. Ward, Jr.
OREGON
ROBERT B. WARD, JR.
JULY 30 1976
1091

Expires 6/30/02

C.S. File No. 65/36-22