

FILED

Date: 3-20-2001 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Apt: 65/36-23

OREGON CORNER RESTORATION FORM

Section 24 Township 20S Range 7W

County Douglas Date 29 Jan 2001

DOUGLAS COUNTY
SURVEYOR

Corner Designation

Section Corner S 13
S 24

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

3 1/4" BLM Brass Cap marked as shown
3/4" Rebar bears S 26° 10' W 2.82'
12" Alder bears S 50 1/4° W 21.6' open face
14" Twin maple N 33° W 38.5' healed face

Monument Detail

Sketch

T20S T20S
S 13
S 24 | R6W
R7W S19
1978

Monument Set (Procedures and Description)

None

New Accessories

12" Maple bears N 08 1/2° E 8.0' blazed, scribed at base "X BT"

Location & Comments

Steel post adjacent
to corner
All bearing trees
have red painted
bends and faces
plus yellow bearing
tree tag.

Compass Declination _____
Firm/Agency ward
Northwest Inc.
Address P O Box 105
Florence OR 97439
Party Chief Rob Ward
Notes 00-61
Witness RON RICE

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Robert B. Ward, Jr.
OREGON
ROBERT B. WARD, JR.
JULY 30 1976
1091

Expires 6/30/02

C.S. File No. 65/36-23