

FILED

Date: 10-1-2001 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/37-23

OREGON CORNER RESTORATION FORM

Section 18 Township 22S Range 11W

County Douglas Date 9/24/01

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

W 1/4 Sec. 18 only

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. M65-4

Monument(s) & Accessories Found: (Condition and Source)

3" Brass Cap on 1" galvanized iron pipe

Record 24" Hem. S 28°W 36.8 ft found down

14" D. Fir stump S 58°E 44.0 ft healed face

Monument Detail

Sketch

T 22 S R 11 W

| •  $\frac{1}{4}$  S 18

1977

R 2 S 10 9 1

Monument Set (Procedures and Description)

none

New Accessories

18" Hem. bears N 3-1/2° W 26.3 ft blazed, scribed  
"X BT"

18" Hem. bears N 84° E 43.1 ft. blazed, scribed  
"1/4 S 18 BT"

Location & Comments

Surveyor's Seal

All bearing trees Compass Declination \_\_\_\_\_  
have a red painted Firm/Agency Ward  
band and face plus Northwest Inc.  
yellow bearing tree address P O Box 105  
tag, 5 1/2' gal. Florence OR 97439  
steel post adjacent Party Chief Rob Ward  
to corner. Notes 01-59  
 Witness Ron Rice

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Robert B. Ward, Jr.  
OREGON  
ROBERT B. WARD, JR.  
JULY 30 1976  
1091

expires 6/30/02

C.S. File No. 65/37-23