

FILED

Date: 10-1-2001 By: JK

This survey consists of

Map. \_\_\_\_\_

Narrative \_\_\_\_\_

Corner Rpt. 65/37-24

OREGON CORNER RESTORATION FORM

Section 18 Township 22S Range 11W

County Douglas Date 9/24/01

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

N 1/16 Sec 18 only

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. M 65-4

Monument(s) & Accessories Found: (Condition and Source)

3" Brass Cap on 1" galvanized iron pipe

Both BT's referenced in M 65-4 missing

Monument Detail

Sketch

T 22S R 11W

| • N 1/16 S 18

1977

RLS 1091

Monument Set (Procedures and Description)

none

New Accessories

12" D. Fir bears N 43° E 38.8 ft blazed, scribed  
"N 1/16 S 18 BT"

11" D. Fir bears S 79-3/4° E 22.2 ft blazed, scribed  
"N 1/16 S 18 BT"

Location & Comments

All bearing trees Compass Declination  
have red painted Firm/Agency ward  
band and face plus Northwest Inc  
yellow bearing tree Address P O Box 105  
tag. 5 1/2' gal. Florence OR 97439  
steel post adjacent Party Chief Rob ward  
to corner. Notes 01-59  
Witness Ron Rice

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Robert B Ward, Jr  
OREGON  
ROBERT B WARD, JR  
JULY 30 1976  
1091

expires 6/30/02

C.S. File No. 65/37-24