



GARY T. SMITHER

Professional Land Surveyor
Certified Water Rights Examiner

FILED

Date: 2/7/2002 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/42-5

DOUGLAS COUNTY
SURVEYOR

Township 21 South, Range 8 West Section 8

North ¼ Corner for Section 8: Found 1945 Brass Cap on Iron Pipe firmly set. Set 6ft. galvanized steel post alongside the Brass Cap.

Old Bearing Trees:

1945 40" Fir, N 11 ½ ° W, 123 links is gone.

1945 40" rotting Fir stump, N 86 ½ ° W, 218 links, no markings.

New Bearing Trees:

15" Maple, N 82° E, 14.9 feet to spike driven in side center, marked "T21 R 8 1/4 S5 BT", with bearing tree tag.

24" D. Fir, N 21° W, 64.0 feet to spike driven in side center, marked "T21 R8 1/4 S5 BT", with bearing tree tag.

15" D. Fir, S 77° W, 70.9 feet to spike driven in side center, marked "T21 R8 1/4 S8 BT", with bearing tree tag.

14" Alder, S 39° E, 30.5 feet to spike driven in side center, bark scribed "T21 R 8 1/4 S8 BT", with bearing tree tag.

Corner Upgrade Jan. 2002

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary T. Smither

OREGON
JANUARY 29, 1991
GARY T. SMITHER
2485

Expires 6/2002