



# GARY T. SMITHER

Professional Land Surveyor  
Certified Water Rights Examiner

FILED

Date: 2/7/2002 By: JC  
This survey consists of:  
Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: 65/42-6

**Township 21 South, Range 8 West  
Section 8**

**DOUGLAS COUNTY  
SURVEYOR**

Southwest Corner for Section 8: Found 1960 Brass Cap on Iron Pipe firmly set with a steel fence post driven alongside the Brass Cap.

**Old Bearing Trees:**

23" D. Fir stump, N 31° E, 35 links, with visible scribe on burnt and rotted face.

18" D. Fir stump, S 54 ¼ ° E, 48 links, burnt and rotted, no markings.

27" Fir stump, S 57 3/4° W, 131 links, gone.

40" D. Fir stump, S 54 ½ ° E, 229 links, with visible scribe on open face and tag.

35" D. Fir stump, N 17° W, 134 links, burnt and rotted with no markings.

17" D. Fir, N 68° E, 323 links, with healed face and tag.

33" D. Fir, N 49° W, 139 links, has fallen over.

28" D. Fir, S 81 ½ ° W, 130 links, has fallen over.

**New Bearing Trees:**

12" D. Fir, S 62° W, 4.1 feet to spike driven in side center, scribed "T21 R8 S18BT", with bearing tree tag.

11" D. Fir, N 32° W, 6.7 feet to spike driven in side center, bark scribed "T21 R8 S7BT", with bearing tree tag.

12" D. Fir, S 43° E, 32.0 feet to spike driven in side center, scribed "T21 R8 S17BT", with bearing tree tag.

*Corner Upgrade Jan 2002*

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Gary T. Smither*

OREGON  
JANUARY 29, 1991  
GARY T. SMITHER  
2485

*Expires 6/2002*

C.S. File No. 65/42-6

FAX and Phone (541) 751-9624  
P.O. Box 545, North Bend, OR 97459