



GARY T. SMITHER

Professional Land Surveyor
Certified Water Rights Examiner

FILED

Date: 2/7/2002 By: J

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/42-8

DOUGLAS COUNTY
SURVEYOR

Township 21 South, Range 8 West Section 8

West ¼ Corner for Section 8: At the ¼ corner 1945 Brass Cap on Iron Pipe firmly set with steel fence post driven alongside the corner.

Old Bearing Trees:

25" burnt and rotting Fir stump, N 85° E, 42 links. Burnt out face with axe marks but no visible scribe.

15" Fir, S 71 ½° W, 76 links is gone. Found 24"x 8" piece of wood with visible scribe.

44" Fir, N 41 ½° E, 174 links, with healed face and tag.

43" Fir, N 84° W, 208 links, with healed face and tag.

New Bearing Trees:

7" D. Fir, S 65° E, 4.3 feet to spike side center scribed "T21 R8 1/4 S8 BT", with new bearing tree tag.

16" D. Fir, N 19° W, 17.8 feet to spike side center scribed "T21 R8 1/4 S7 BT" with new bearing tree tag.

Corner Upgrade Dec 2001

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary T. Smither

OREGON
JANUARY 29, 1991
GARY T. SMITHER
2485

Expires 6/2002