

OREGON CORNER RESTORATION FORM

Corner No. 2

Section 27 Township 32S Range 7W

County Douglas Date March, 2002

Corner Designation

W 1/16 527
 534

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Corner Set by L. Van Swearingen, PE, 1961, Map M21-61.

Monument(s) & Accessories Found: (Condition and Source)

Found Drill Steel in mound of stone, from which a:
30" D. Fir BT, face overgrown, bears N6°W,
35' feet (record 34' feet),
18" Live Oak BT, scribes visible, bears South,
56' feet (record 54' feet).

Monument Detail

Sketch

(Drill Steel Only)

FILED
 Date: 3/27/2002 By: X
 This survey consists of:
 Map: M137-35
 Narrative:
 Corner Rpt: 65/42-1A RW 39

DOUGLAS COUNTY SURVEYOR

Monument Set (Procedures and Description)

N/A

New Accessories

Set 6 foot steel fence post, East, 10 feet.

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner

Engineering

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Ben Schneider

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Bruce Shaner
 OREGON
 OCT. 4, 1957
 BRUCE A. SHANER
 490

Renews June 30,

C.S. File No 65/42-12 2002