

OREGON CORNER RESTORATION FORM

CORNER No. 24

Section 27 Township 32S Range TW

County Douglas Date March, 2002

Mining claim  
Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Briggs, U.S.G.L.O., 1901 Survey Plat

RLS Van Swearingen, Map No. M21-61, 1961 Survey.

Monument(s) & Accessories Found: (Condition and Source)

Found 3/4" Iron Pipe w/ Brass Washer, LS 33 (Price), from  
which a: overgrown

30" Madrone BT, new snag, with old face, bears 520°E,  
15 Feet to face.

32" Madrone BT, new snag, face overgrown, bears N85 1/2°E,  
56 feet.

18" D. Fir BT, scribes visible, bears 533°E, 29 1/2 feet.

8" D. Fir BT, scribes visible, bears N42°W, 10 1/2 feet.

Monument Detail

Sketch

(No Record of  
D. Fir BT's.)

FILED

Date: 3/27/2002 By: X

This survey consists of:

Map: M137-35

Narrative: \_\_\_\_\_

Corner Rpt: 65/42-11 thru 39

Monument Set (Procedures and Description)

DOUGLAS COUNTY  
SURVEYOR

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner

Engineering

Address P.O. Box 1430

Roseburg, Oregon 97470

Party Chief B. Shaner

Notes \_\_\_\_\_

Witness Rav Schneider

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A Shaner  
OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

Renews June 30,

C.S. File No. 65/42-34 2002