


OREGON CORNER RESTORATION FORM

CORNER No. 26

Section 27 Township 32S Range TW

County Douglas Date March, 2002

Mining Claim  
Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. \_\_\_\_\_

Briggs, U.S.G.L.D., 1901 Survey Plat

RLS Van Swearingen, Map No. 21-61, 1961 Survey.

Monument(s) & Accessories Found: (Condition and Source)

Found Drill Steel from which a:

20" Madrone, original BT, old face, bears S36°E (U.S. record = S62°E), 70 feet.

12" D. Fir BT, face overgrown, bears S67 1/2°W, 10<sup>B</sup> feet.

10" D. Fir BT, " " , bears S10°E, 13 1/2 feet.

Monument Detail

Sketch

FILED

Date: 3/27/2002 By: X

This survey consists of:

Map: M 137-35

Narrative: \_\_\_\_\_

Corner Rpt: 65/42-11 thru 39

DOUGLAS COUNTY  
SURVEYOR

Monument Set (Procedures and Description)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

6 Foot Steel Fence Post bears S30°W, 10 feet.

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner Engineering

Address P.O. Box 1430 Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Ben Schneider

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A. Shaner

OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

Expires June 30,

2002

C.S. File No 65/42-36