


OREGON CORNER RESTORATION FORM

CORNER No. 29

Section 27 Township 32S Range TW

County Douglas Date March, 2002

Mining Claim
Corner Designation



- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Briggs, U.S.G.L.D., 1901 Survey Plat

Monument(s) & Accessories Found: (Condition and Source)

Corner Not Found & apparently obliterated in distant past.

We made several diligent searches, to no avail.

BSJ

Monument Detail

Sketch

Filed
 Date: 3/27/2002 By: JC
 This survey consists of:
 Map: M137-35
 Narrative: _____
 Corner Rpt: 65/42-11 Thru 39

DOUGLAS COUNTY
SURVEYOR

Monument Set (Procedures and Description)

New Accessories

Location & Comments

Surveyor's Seal

Compass Declination 20°E

Firm/Agency Shaner Engineering

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Ben Schneider

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Bruce A. Shaner
 OREGON
 OCT. 4, 1957
 BRUCE A. SHANER
 430

Renews June 30,

C.S. File No. 65/42-39

2002