

FILED

Date: 8-13-2002 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt. 65/44-10

OREGON CORNER RESTORATION FORM

Section 35 Township 24 S Range 6 W

County DOUGLAS Date AUG. 7, 2002

DOUGLAS COUNTY
SURVEYOR

Corner Designation

C 1/4 SEC. 35 T24S R6W

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. 540140

Monument(s) & Accessories Found: (Condition and Source)

5/8" IRON ROD - OK IN DOWN FENCELINE

7" OAK SNAG WITH CLOSED FACE BEARS S74E, 9'

10" OAK STUMP - ROTTED, NO MARKS REMAINING BEARS N26E, 20'

FENCE CORNER - OKAY - BEARS SOUTH, 20'

18" OAK (RECORD 5') - FAIR - BEARS SOUTH, 3'

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

14" WHITE OAK BEARS S49E, 212 SCRIBED "C 1/4 S35 BT"

9" WHITE OAK BEARS S69W, 154 SCRIBED "C 1/4 S35 BT"

Location & Comments

Surveyor's Seal

Compass Declination 18°


Firm/Agency ROSEBURG FOREST PRODUCTS

Address Highway 99 S DILLARD, OR

Party Chief R. McMANIS

Notes _____

Witness _____



C.S. File No 65/44-10

Renews 6/30/04