

FILED

Date: 11-6-2002 By: SC

This survey consists of:

OREGON CORNER RESTORATION FORM

Section: 20 Township: 20S Range: 11W

County: Douglas Date: 9/09/02

Com: 65/44-20

DOCUMENT BY SURVEYOR

Corner Designation

S1/16 S20 & S21

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.:

A 1967 survey by Ron Durham (M35-74).

Monument(s) & Accessories Found: (Condition and Source)

Fd. 2" aluminum pipe.

54" Fir stump bears S7°E 51.3 ft. (record 53.8 ft.), visible bark scribe "1/16 BT".

Monument Detail:

Sketch:

Monument Set (Procedures and Description):

New Accessories:

12" Fir bears S11°E 28.7 ft., scribed "1/16 S21 BT".

19" Alder bears S88°W 38.9 ft., bark scribed "1/16 S20 BT".

Location and Comments:

Distance measured to a spike set at side center on new BT's. BT tag nailed to tree facing the corner.

Compass Declination: 18°E
Firm/Agency: Menasha Forest Products Corporation
Address: P.O. Box 588 North Bend, OR 97459

Party Chief: Brent Bacon
Notes: Doyce Rose

Witness: _____

Surveyor's Seal

REGISTERED PROFESSIONAL LAND SURVEYOR

Brent W. Bacon

OREGON
JULY 14, 1998
BRENT W. BACON
2 8 6 9