

FILED

Date: 11/12/2002 By: JP

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 65/44-24

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section _____ Township 21 S Range 8 W

County Douglas Date 10-25-02

Corner Designation

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

END: 2 1/2" GLO Brass Cap with the following

32" x 4' Fir Stump bears N 37° E 261ks (OBT) no marks

40" Fir Snag bears N 10° W 261ks (OBT) no marks

40" x 3' Fir Stump bears S 13° 45' W, 1351ks no marks

Visible raised mound of stone, west of corner

Monument Detail

Sketch

T 21 S R 8 W

S 21	S 22
S 28	S 27
1945	

Monument Set (Procedures and Description)

New Accessories set by BLM

11" Douglas Fir bears S 45° E, 8° Ft open face

12" Douglas Fir bears S 51 3/4° W, 22° Ft open face

18" Douglas Fir bears N 37 3/4° W, 40 3/4° Ft open face

18" Douglas Fir bears N 19 3/4° E, 27 1/2° Ft open face

Location & Comments

Surveyor's Seal

Compass Declination _____

Firm/Agency _____

Ward Northwest Inc.


Address P.O. Box 105

Florence OR

Party Chief _____

Notes _____

Witness Ben Pastor



EXPIRES: 12/31/02

C.S. File No 65/44-24