

FILED

Date: 12-2-2002 By: X

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/44-25

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 6 Township 31S Range 3W

County Douglas Date 11/19/02

Corner Designation

1/7 COR SECTIONS 6 & 7

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. 190600

Monument(s) & Accessories Found: (Condition and Source)

1/2" IRON PIPE, 1 1/4" IRON PIPE WITH BRASS CAP AND ORIGINAL STONE

27" FIR SNAG BEARS S. 39° W. 26 1/4'


20" FIR SNAG BEARS S. 36° E. 16 1/2'

20" FIR WITH HEALED FACE BEARS N. 21° W. 5 3/4'

14" FIR WITH HEALED FACE BEARS S. 32° W. 24 1/4'

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

12" DOUG. FIR BEARS N. 65° E. 4 1/2 FT. SCRIBED "156 BT"

9" DOUG. FIR BEARS S. 41° E. 25 1/2 FT. SCRIBED "757 BT"

Location & Comments

1/2" IRON PIPE AND QUARTZ Compass Declination 19° E

STONE ALONGSIDE IRON Firm/Agency ROSEBURG

PIPE WITH BRASS CAP FOREST PRODUCTS

Address OLD HWY 99,

DILLARD ORE

Party Chief R. McMANIS

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Mark F. Smalley

OREGON
JULY 26, 1988
MARK F. SMALLEY
2354

RENEWS 6/30/04

C.S. FILE NO 65/44-25