

FILED

Date: 12/16/2002 By: JC

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: 65/44-28

DOUGLAS COUNTY  
SURVEYOR

**OREGON CORNER RESTORATION FORM**

Section: 1 Township: 21S Range: 12W

County: Douglas Date: 10-17-02

**Corner Designation**

CE 1/16 S1

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

**Previous Renewals/Surveys, etc.:**


Survey in 1980 by Richard Hintz (M79-30).

**Monument(s) & Accessories Found: (Condition and Source)**

Fd. 2½" Brass cap cemented in sandstone, marked: "PLS 497 T21S R12W CE 1/16 1979".  
 16" Fir, S22°W 17.5 Ft., healed face.  
 Metal fence post, S71°W 3.3 Ft.

**Monument Detail:**

**Sketch:**



**Monument Set (Procedures and Description):**

**New Accessories:**

16" Fir, N31°W 30.3 Ft., scribed "1/16S1BT".


**Location and Comments:**

Distance measured to  
 spike set at side center  
 on new BT. Tag nailed  
 to BT facing the corner.

Compass Declination: 18°E  
 Firm/Agency: Menasha  
Forest Products Corp.  
 Address: \_\_\_\_\_  
PO Box 588  
North Bend, OR 97459  
 Party Chief: Brent Bacon  
 Notes: Doyce Rose

Witness: \_\_\_\_\_

**Surveyor's Seal**



*Brent W. Bacon*



Renews 12-31-2003

C.S. File No 65/44-28