

FILED

Date: 7/23/2002 By: JP

This survey consists of:

Map: M 140-41

Narrative: \_\_\_\_\_

Corner Rpt: CS 65/44-7E

OREGON CORNER RESTORATION FORM

Section 26 Township 32S Range 4W

County Douglas Date July 22, 2002

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

1/4 523  
526

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.

P.L.S. Gerald Nygren, 1989, C.S. File 63/51

Monument(s) & Accessories Found: (Condition and Source)

Found 5/8" x 30" Iron Rod, from which are:  
3" D. Fir BT, now dead & down, bears N80°W, 25<sup>3</sup> feet,  
14" D. Fir BT, face of growth, bears N58°W, 22<sup>7</sup> feet (record  
12" D. Fir BT, " " , bears S22°E, 16<sup>5</sup> FT. (26<sup>3</sup> feet)  
18" D. Fir BT, " " , bears N26°E, 5<sup>2</sup> Ft.

Monument Detail

Sketch

None.

Monument Set (Procedures and Description)

None.

New Accessories

6 Foot Steel Fence Post bears West, 10 Ft.

Location & Comments

Corner lays on  
old cat road,  
runs West from  
corner.

Compass Declination 20°E

Firm/Agency Shaner

Engineering, Inc.

Address P.O. Box 1430

Roseburg, OR 97470

Party Chief B. Shaner

Notes " "

Witness Rox Schneider

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Bruce A. Shaner

OREGON  
OCT. 4, 1957  
BRUCE A. SHANER  
430

Renews June 30  
2004

C.S. File No 65/44-7E