

Date 2/25/2003 by JC

OREGON CORNER RESTORATION FORM

Section 30 Township 21S Range 8W

County Douglas Date 2/19/03

Monument           
Name           
Corner 65/45-7

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

Section Corner for 19,  
30 only. (West)

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.         

Monument(s) & Accessories Found: (Condition and Source)

- 16" D. fir, bears N64°E, 7.3 ft., healed face
- 18" D. fir, bears S59°E, 19.1 ft., healed face
- 17" D. fir, bears N6°E, 26.3 ft., healed face
- 14" D. fir, bears S62°E, 4.8 ft., healed face
- 19" D. fir, bears S4°E, 16.7 ft., healed face
- 15" D. fir., bears N59°W, 21.0 ft., healed face

Monument Detail

Sketch

T21S T21S  
 R9W S19  
 S24 S30  
       R8W  
 1945

Monument Set (Procedures and Description)

NONE

New Accessories

NONE

Location & Comments

-B.T.'s painted and tagged

-Monument pipe is bent. All B.T.'s measured to where pipe enters ground.

Compass Declination         

Firm/Agency Ward Northwest Inc


Address PO Box 105 Florence OR 97439

Party Chief Ron Rice

Notes         

Witness Ben Pastor

Surveyor's Seal



EXPIRES: 12/31/04

C.S. File No 65/45-7