

FILED

Date: 8-19-2003 P.V. SC

This survey consists of:

Map: _____

Name: _____

Corner Rpt: 65/48-3

CORNER REPORT FORM

Section 10 _____ Township 24 _____ Range 7 _____

Douglas County Date July 31, 2003

CORNER DESIGNATION
only

Condition **DEPARTMENT OF COUNTY SURVEYOR**

Not Found

Renewed

Unrecorded

Surveyed In

Referenced out

Southeast corner section 10

Previous Renewals/Surveys, etc:

Monument(s) & Accessories Found: (Condition and Source)

"+" on stone w/ 2 notches on east and 4 on south
"+ S10" on vertical face N 68°W 9.9 feet
10" w. oak BT now 12", N 75°E 33.0', scar vis., tag
20" fir BT now 32", S 24°W 25.3' (27.1), scar vis., tag (DSCO 1958)
22" w. oak BT, S 79°E 18.5', holes in tree, rotting, tag (re-scribed 1958 by DCSO)
18" w. oak BT now 20", S 43°W 12.5', swell vis., tag
All by Whipple in 1893 or as noted

Monument Detail

Sketch

Monument Set (Procedures and Description)

None

New Accessories

None

Location & Comments

Surveyor's Seal



Exp 6/30/04

Compass Declination
Firm/Agency: Sweeden Land Surveying
Address: 5211 Cole Road, Oakland, OR. 97462
Party Chief: C. Sweeden
Notes:
Witness: E. Wilds

C.S. File No 65/48-3