

Date SEP 4 2003 By: JC

OREGON CORNER RESTORATION FORM
Section 11 Township 25S Range 2W
County DOUGLAS Date MAY 2003

This survey consists of:
Map: _____
Name: _____
Corner Rpt: 65/48-6
DOUGLAS COUNTY
SURVEYOR

Corner Designation
1/4 S10/S11

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)
1962 STEEL PIPE AND BRASS CAP
 BTs: 17" HEMLOCK S24 1/2 E 23.1' No FACE
40" CEDAR S64 E 35.6' FOUND FACE CHOPPED INTO
57" FIR STUMP N52W 26.4' FOUND FACE CHOPPED INTO

Monument Detail



Sketch

Monument Set (Procedures and Description)

New Accessories
BT 15" HEMLOCK S18W 11.6' Scribed "1/4 S BT"

Location & Comments
BLAZED LINES SOUTH, EAST, AND NORTH
 Compass Declination 20
 Firm/Agency Roseburg Forest
 Products _____
 Address PO Box 1088
Roseburg Oregon 97470
 Party Chief Bill Olson
 Notes _____
 Witness Mike Froudehl

Surveyor's Seal



RENEWS 6/30/04

C.S. File No 65/48-6