

FILED

Date: 11-7-2003 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65 | 48-34

OREGON CORNER RESTORATION FORM

Section 3 Township 20S Range 11W

County DOUGLAS Date 10/22/03

Corner Designation

SOUTHWEST CORNER

DOUGLAS COUNTY
SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

2 1/4" IRON PIPE WITH BRASS CAP DATED 1975

RUSTED METAL POST WITH U.S.F.S. BOUNDARY TAG

50" FIR BEARS N 2° E, 69.7' BARK SCRIBING VISIBLE

60" FIR BEARS N 7 1/2° W, 59.2' HEALED FACE

32" FIR BEARS S 27° E, 3.5' HEALED FACE

34" FIR BEARS S 16° W, 26.0' HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

SET 4" POST ADJACENT TO CORNER

Location & Comments

ALL BT'S HAVE RED Compass Declination _____

PAINTED BAND AND Firm/Agency _____

FACE WITH YELLOW WARD NORTHWEST, INC

BT TAG. Address 239 NOPAL ST

FLORENCE OR 97439

Party Chief RON RICE

Notes JOB # 03-75

Witness BEN PASTOR

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald L. Rice

OREGON
JULY 9, 2002
RONALD L. RICE
#54633 LS

EXPIRES: 12/31/04

C.S. File No 65/48-34