

FILED

Date: 11-7-2003 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/48-36

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 3 Township 20S Range 11W

County DOUGLAS Date 10/22/03

Corner Designation

SOUTH 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

Monument(s) & Accessories Found: (Condition and Source)

1 1/4" IRON PIPE WITH 2 1/2" BRASS CAP DATED 1970
39" FIR BEARS S18 1/4°W, 33.7' HEALED FACE
20" FIR BEARS N70°W, 10.4' HEALED FACE
5" X 6" FIR STUMP BEARS N56°W, 29.0' HEALED FACE

Monument Detail

Sketch

Monument Set (Procedures and Description)

New Accessories

17" ALDER BEARS S25°E, 9.3' BARK SCRIBED "1/4 S10 BT"
SET 4' POST ADJACENT TO CORNER

Location & Comments

ALL BT'S HAVE RED Compass Declination _____
PAINTED BAND AND Firm/Agency _____
FACE WITH YELLOW WARD NORTHWEST, INC
BT TAG Address 239 NOPAL ST.
FLORENCE OR 97439
 Party Chief RON RICE
 Notes JOB# 03-75
 Witness BEN PASTOR

Surveyor's Seal



C.S. File No 65/48-36