

FILED

Date: 11-14-2003 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/48-44

DOUGLAS COUNTY
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 16 Township 31S Range 8W

County DOUGLAS Date 10-14-03

Corner Designation

1/4
S17 | S16

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

BLM LINE NOTES, page 13211

Monument(s) & Accessories Found: (Condition and Source)

1962 BLM IPBC

BTs: 23" FIR S37 1/2 E 29.5' TO NAIL (RECORDED 30.4') GOOD-HEALED

ORIG FIR EAST 40.9' STUMP

ORIG 47" FIR WEST 34.7' TO NAIL (RECORDED 33.7') PARTIAL SCRIBE

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

BTs: 16" FIR S57W 23.5' SCRIBED "1/4 S BT"

15" FIR N80W 20.6' SCRIBED "1/4 S BT"

Location & Comments

Compass Declination 19°

Firm/Agency Roseburg

Forest Products

Address PO Box 1088

Roseburg Oregon

Party Chief Bill Olson

Notes _____

Witness Mike Fromdahl

Surveyor's Seal



RENEWS 6/30/04

C.S. File No 65/48-44