

FILED

Date: 3-5-2004 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/49-10

OREGON CORNER RESTORATION FORM

Section: 20 Township: 20S Range: 11W

County: Douglas Date: 12/19/03

DOUGLAS COUNTY
SURVEYOR

Corner Designation

E 1/16 S20 & S29

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc.:


Set in unrecorded survey by Gleason & Lamm, used in unrecorded 1964 survey by Walter Camp for U.S. Plywood, used in a 1967 survey by Ron Durham (M35-74 & CS 55/65).

Monument(s) & Accessories Found: (Condition and Source)

Fd. 2" aluminum pipe.
 45" Spruce stump, S24°E 12.5FT (record 8.6FT).
 76" Spruce stump, N79°W 8.5FT (record 12.7FT).

Monument Detail:

Sketch:



Monument Set (Procedures and Description):

New Accessories:

10" Hemlock, N83°E 11.0FT, scribed "E1/16S20BT".

Location and Comments:

Distance measured to spike set at side center on new BT. BT tag attached to the tree facing the corner.

Compass Declination: 18°E
 Firm/Agency: Menasha Forest Products Corp.
 Address: PO Box 588 North Bend, OR 97459
 Party Chief: Brent Bacon
 Notes: Doyce Rose
 Witness: _____

Surveyor's Seal

