

**Township 21 South, Range 8 West
Section 32**

NE Corner Section 32: Found 1945 Witness Corner, Brass Cap on Iron Pipe firmly set. We Set a 6 foot galvanized steel fence post alongside with top painted red. This corner is N 0°35'E, 1.30 chains from a 2 ½ inch aluminum cap established at the true Section Corner in 2001 by Ward, properly marked and firmly set. We Set a 6 foot galvanized steel fence post alongside with top painted red.

Old Bearing Trees Taken in 1945 to Witness Corner by GLO:

44"rotted Fir Stump, N 1°45' E, 165 links From WC, no marks, no tag.

44"rotted Fir Stump, S 31° E, 106 links From WC, no marks, no tag.

28"rotted Fir Stump, S 39° W, 70 links From WC, no marks, no tag.

44"rotted Fir Stump, N 0°45' W, 271 links From WC, no marks, no tag.

Bearing Trees Taken in 2001 to True Corner Monument:

9" D. Fir, N 65° E, 3.8 feet to spike side center, with visible scribe and aluminum tag

13" D. Fir, S 30° E, 9.3 feet to spike side center, with visible scribe and aluminum tag

12" D. Fir, S 68° W, 8.7 feet to spike side center, with visible scribe and aluminum tag

10" D. Fir, N 80° W, 19.9 feet to spike side center, with visible scribe and aluminum tag
(Rec N. 88° W)

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Gary T. Smither

OREGON
JANUARY 29, 1991
GARY T. SMITHER
2485

Expires 6/04

FILED

Date: 3/8/2004 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 65/49-19

DOUGLAS COUNTY
SURVEYOR

300200

rec'd Feb 2004

C.S. File no 65/49-19