

FILED

Date: 12/9/2004 By: JC

This survey consists of:

Corner 65/52-18

OREGON CORNER RESTORATION FORM

Section 18 Township 28 Range 8W

County Douglas Date 12/3/04

DOUGLAS COUNTY
SURVEYOR

CORNER DESIGNATION

1/4 Corner common to
Sections 7 and 18

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. _____

1875 G.L.O. survey by W.S. Chapman.

1972 B.L.M. resurvey by Lynn Roseberry.

Monument(s) & Accessories Found: (Condition and Source)

Found 1972 B.L.M. brass disk in solid rock.

Monument Detail

Sketch

Monument Set (Procedures and Description)

N/A

New Accessories

11" diam. D. Fir N.59°W., 18.4 feet scribed "1/4 S7 BT"

13" diam. D. Fir N.29°E., 15.6 feet scribed "1/4 S7 BT"

6 foot steel post set North 8 feet.

Location & Comments

steep south slope

South of high voltage
power lines.

Compass Declination 18°E

Firm/Agency David Edwards Land Surveying

Address P.O. Box 361

Oakland, OR. 97462

Party Chief Brant Miller

Notes _____

Witness _____

Surveyor's Seal

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David A. Edwards

OREGON
JULY 26, 1988
DAVID A. EDWARDS
2339

Renews 12/31/05

C.S. File No 65/52-18