

FILED

Date: 9-18-2007 By: JC

This survey consists of:

Map: \_\_\_\_\_

North of: \_\_\_\_\_

Corner Rpt: 65/52-24

**OREGON CORNER RESTORATION FORM**

Section 23 Township 26 S Range 8 W

County DOUGLAS Date 8/30/2007

Corner Designation

S 1/16 ~~S22~~ 23  
S22

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

DOUGLAS COUNTY  
SURVEYOR

Previous Renewals/Surveys, etc. Robert C. Adamek Aug. 18 1975 M57-74  
Nick Juliano May 9, 1972 M57/74 C.S. file 55/251

Monument(s) & Accessories Found: (Condition and Source)  
Found 3/4" Iron Pipe in good condition 1.0 feet above ground on a steep North facing slope  
Found a 28" DF S 63°26'E 5.8 feet. (Record S68°E 5.0 feet)

Monument Detail

Sketch

**BLAZED PAINTED TAGGED**  
**LRT MEASURED**  
**RECORD MEASURED**


//////  
<LRT 2007>  
(ADAMEK 1975)

LRT  
S 23

See CS 65/52-22  
or CS 65/52-23  
for correct sketch

S22 | S23  
S27 | S26

<N88°42'13"E 1384<sup>35</sup>>  
(N88°41'24"E 1384<sup>35</sup>)



Monument Set (Procedures and Description)

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

New BT

7" Douglas Fir N 78°32' E 11.25feet. Scribed S1/16 S 23 BT and Tagged Tree.

Location & Comments

Found a 3/4" Iron Pipe  
in good condition  
1.0 feet above ground  
on steep North facing  
slope approximately  
48 feet North of rock  
bluff.

Basis of Bearing Solar  
Firm/Agency Lone Rock Timber  
Management Co.  
Address PO BOX 1127  
Roseburg OR 97470  
Party Chief Ken Hoffine  
Notes Jason Moon  
Witness Ignacio Roman

Surveyor's Seal

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ken W Hoffine*

OREGON  
JULY 18, 1987  
KEN W. HOFFINE  
2291

Expires 6-30-09

C.S. File No 65/52-24