

FILED

Date: 2-14-2005 By: JC

This survey consists of:

Map: \_\_\_\_\_

Name: \_\_\_\_\_

Corner Rpt: 65/54-4

DOUGLAS COUNTY  
SURVEYOR

OREGON CORNER RESTORATION FORM

Section 36 Township 29S Range 7W

County DOUGLAS Date 1-7-05

Corner Designation

S 1/4

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals/Surveys, etc. 640100

Monument(s) & Accessories Found: (Condition and Source)

BLM I.P.B.C. SOLID IN ROCK MOUND


20" W. OAK N23W 38° HEALED (BLM - N22°W)

30" CEDAR S18E 39° HEALED

67" PINE STUMP N40E 141° ROTTEN

Monument Detail

Sketch



Monument Set (Procedures and Description)

New Accessories

BTs:

11" CEDAR S18W 9° Scribed "1/4 SBT"

10" CEDAR N72W 58° Scribed "1/4 SBT"

Location & Comments

Surveyor's Seal

Compass Declination 19°


Firm/Agency ROSEBURG RESOURCES CO.

Address PO Box 1088 ROSEBURG OREGON 97470

Party Chief Bill Olson

Notes \_\_\_\_\_

Witness \_\_\_\_\_



Renews 6/30/06

C.S. File No 65/54-4