



505 SE MAIN STREET
POST OFFICE BOX 1271
ROSEBURG, OR 97470

(541) 673-0166
FAX: (541) 440-9392

FILED

Date: 12-9-2005 By: X
for This survey consists of:
Map: V. 21 Pg 48C
Name:
Corner: 65/55-11
DOUGLAS COUNTY
SURVEYOR

December 6, 2005

Douglas County Surveyor's Office
Courthouse Room 105-A
Roseburg, Oregon 97470

ATTN: Romey Ware

RE: Taft Subdivision, Phase 3 (Volume 21, Page 48)

Dear Romey:

The westerly common lot corner to Lots 74 and 75 was destroyed during construction. Our survey crew held control and monuments that were used in setting monuments for the plat of "Taft Subdivision, Phase 3" to recreate the location of the westerly common lot corner to Lots 74 and 75. A "PK Nail" was placed at the original location in the concrete on top of a manhole.

Sincerely,

Ronald A. Quimby,
P.L.S. #1654

C.S. File No 65/55-11